

RELIABILITY MONITOR

JOB	PRODUCT	DESCRIPTION	FA NO	UNIT	TEST MODE	FAIL MECHANISM	CORRECTIVE ACTION
P18923	DS12887	BIASED MOISTURE	970059				
P18949	DS2175S	I/L, 48HR BIASED	970027	1	ICC	LATCH-UP	No Corrective Action Required. Condition Occurred in Accelerated Testing. Failure has been removed from RMP.
P19043	DS5000T	TEMP CYCLE	970156				
P19044	DS5000T	MOISTURE SOAK	970181				
P19112	DS1868E	I/L, 48HR BIASED	970050	1	OUTPUT LEAKAGE LOW	LATCH-UP	No Corrective Action Required. Condition Occurred in Accelerated Testing. Failure has been removed from RMP.
P19131	DS2181A	I/L, 48HR BIASED	970076				
P19146	DS1302Z	I/L, 48HR BIASED	970056	1	ICC ACTIVE	UNKNOWN	None Possible
P19168	DS2181A	HIGH VOLTAGE LIFE	970063	1	FUNCTIONALITY	LATCH-UP	No Corrective Action Required. Condition Occurred in Accelerated Testing. Failure has been removed from RMP.
P19260	DS1669S	TEMP CYCLE	970214	1	WIPER RESISTANCE	HIGH CURRENT CONDITION	No Corrective Action Required. Condition occurred as a result of EOS or Latchup during Testing. Failure has been removed from RMP.
P19834	DS1669S	HIGH TEMP STORAGE	970213				
P20685	DS80320	I/L, 48HR BIASED	970266				