

Assembler : UTL

Solderability Backward Compatability monitoring for Oct'07
Meco 02

| Package group | MSOP | SOT | SC70 | QFN | TQFN |
|----------------------|------|-------|------|------|-------|
| Lot rej./Lot insp. | 0/9 | 0/17 | 0/2 | 0/4 | 0/16 |
| % LRR | 0 | 0 | 0 | 0 | 0 |
| Unit rej./Unit insp. | 0/99 | 0/187 | 0/22 | 0/44 | 0/176 |
| PPM | 0 | 0 | 0 | 0 | 0 |

Meco 03

| Package group | SOIC | QSOP |
|----------------------|------|------|
| Lot rej./Lot insp. | 0/7 | 0/2 |
| % LRR | 0 | 0 |
| Unit rej./Unit insp. | 0/77 | 0/22 |
| PPM | 0 | 0 |

Meco 04

| Package group | QFN | TQFN | TDFN | UDFN |
|----------------------|------|-------|------|------|
| Lot rej./Lot insp. | 0/4 | 0/19 | 0/6 | 0/1 |
| % LRR | 0 | 0 | 0 | 0 |
| Unit rej./Unit insp. | 0/44 | 0/209 | 0/66 | 0/11 |
| PPM | 0 | 0 | 0 | 0 |

Meco 05

| Package group | SOIC | TSSOP | QSOP |
|----------------------|------|-------|------|
| Lot rej./Lot insp. | 0/5 | 0/2 | 0/1 |
| % LRR | 0 | 0 | 0 |
| Unit rej./Unit insp. | 0/55 | 0/22 | 0/11 |
| PPM | 0 | 0 | 0 |

Assembler : UTL

Solderability Backward Compatability monitoring for Nov'07
Meco 02

| Package group | MSOP | SOT | SC70 | QFN | TQFN |
|----------------------|------|-------|------|------|-------|
| Lot rej./Lot insp. | 0/8 | 0/10 | 0/4 | 0/4 | 0/14 |
| % LRR | 0 | 0 | 0 | 0 | 0 |
| Unit rej./Unit insp. | 0/88 | 0/110 | 0/44 | 0/44 | 0/154 |
| PPM | 0 | 0 | 0 | 0 | 0 |

Meco 03

| Package group | SOIC | QSOP |
|----------------------|------|------|
| Lot rej./Lot insp. | 0/6 | 0/3 |
| % LRR | 0 | 0 |
| Unit rej./Unit insp. | 0/66 | 0/33 |
| PPM | 0 | 0 |

Meco 04

| Package group | QFN | TQFN | TDFN |
|----------------------|------|-------|------|
| Lot rej./Lot insp. | 0/4 | 0/17 | 0/1 |
| % LRR | 0 | 0 | 0 |
| Unit rej./Unit insp. | 0/44 | 0/187 | 0/11 |
| PPM | 0 | 0 | 0 |

Meco 05

| Package group | SOIC | TSSOP | QSOP |
|----------------------|------|-------|------|
| Lot rej./Lot insp. | 0/4 | 0/2 | 0/6 |
| % LRR | 0 | 0 | 0 |
| Unit rej./Unit insp. | 0/44 | 0/22 | 0/66 |
| PPM | 0 | 0 | 0 |

Assembler : UTL

Solderability Backward Compatability monitoring for Dec'07
Meco 02

| Package group | MSOP | SOT | SC70 | QFN | TQFN | UQFN |
|----------------------|-------|-------|------|------|-------|------|
| Lot rej./Lot insp. | 0/10 | 0/13 | 0/1 | 0/4 | 0/10 | 0/2 |
| % LRR | 0 | 0 | 0 | 0 | 0 | 0 |
| Unit rej./Unit insp. | 0/110 | 0/143 | 0/11 | 0/44 | 0/110 | 0/22 |
| PPM | 0 | 0 | 0 | 0 | 0 | 0 |

Meco 03

| Package group | SOIC | QSOP |
|----------------------|------|------|
| Lot rej./Lot insp. | 0/4 | 0/2 |
| % LRR | 0 | 0 |
| Unit rej./Unit insp. | 0/44 | 0/22 |
| PPM | 0 | 0 |

Meco 04

| Package group | SOT | QFN | TQFN | TDFN |
|----------------------|------|------|-------|------|
| Lot rej./Lot insp. | 0/1 | 0/4 | 0/16 | 0/3 |
| % LRR | 0 | 0 | 0 | 0 |
| Unit rej./Unit insp. | 0/11 | 0/44 | 0/176 | 0/33 |
| PPM | 0 | 0 | 0 | 0 |

Meco 05

| Package group | SOIC | QSOP |
|----------------------|------|------|
| Lot rej./Lot insp. | 0/6 | 0/1 |
| % LRR | 0 | 0 |
| Unit rej./Unit insp. | 0/66 | 0/11 |
| PPM | 0 | 0 |